# Richmond Refinery LPS Alert - Safety

### Contractor Rolls Ankle





Impact ERM: 42843

Location:

**B&S - Quarry Tank Field** 

#### **Contact Information:**

Phil Sweet 510-242-1897 pwsw@chevron.com



Work area in the Quarry Tank Field



Example of a rock the contractor rolled his ankle on

Always remember to do your LPSA – because we care about you!

## **Incident Description:**

On August 1<sup>st</sup> a contract employee rolled his left ankle on some loose rock while walking in the Quarry Tank Field area near T-3105 where rock crushing equipment was being shut down for the day. This injury has been classified as recordable.

### **Immediate Actions Taken:**

- 1. Contractor was taken to refinery clinic for review by the onsite Physician.
- 2. The contractor was taken to an off-site facility for follow-up care.
- 3. Entire crew had a safety stand down and discussed uneven footing around the rock crushing area.

### Considerations:

- 1. Always perform an LPSA for every task, including routine tasks.
- Does my LPSA consider the risks associated with walking/working surfaces?
- 3. Consider alternative routes to walk safely.
- 4. Always keep your eyes on the path ahead.



This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.